



## SALES BULLETIN

September 25, 2017

TO: Suburban RV Stocking Distributors and Recommended Service Centers

FROM: Steve Gokie

### SF-Q and SF-FQ ELECTRODE WIRE ASSEMBLY CHANGE



Based on Suburban's commitment to continuous improvement a change was made to SF-Q and SF-FQ furnaces.

On models SF20/25/30/35Q and SF20/25/30/35FQ furnaces, the electrode wire assembly has been changed to part number 233222 effective April 3, 2017 (04-03-2017). This production change also includes the removal of the two top secondary plates and tinnerman clip.

The SF42Q and SF42FQ model will continue to use part number 232286 electrode and wire assembly.

**PLEASE NOTE:** parts are not interchangeable or backward compatible. Part number 233222 must be installed on SF20/25/30/35Q and SF20/25/30/35FQ furnace models. NOTE: The photos below are used to illustrate the electrode design change.

If you have any questions please contact Customer Service at 423 775-2131 extension 7101 concerning this part number change.



This manual has been provided courtesy of  
My RV Works, Inc.

[www.myrvworks.com](http://www.myrvworks.com)



You can find more RV service manuals here:

[www.myrvworks.com/manuals](http://www.myrvworks.com/manuals)

Over the years of running a mobile RV repair service, having a dedicated place to access service manuals for all the different appliances and components found on RVs was something that I always had a desire to create.

I hope this resource makes your RV repairs easier, as it has mine, but please be careful and follow proper safety practices when attempting to repair your own RV.

If in doubt, please consult with a professional RV technician!



DARREN KOEPP - OWNER, MY RV WORKS, INC.

*All service manuals provided on [www.myrvworks.com](http://www.myrvworks.com) are believed to be released for distribution and/or in the public domain.*